EXHIBIT 38

PARTIES AND JURISDICTION

- 1. The Plaintiffs RUBEN JUAREZ and ISELA HERNANDEZ reside in Granada Hills, CA 91344, in the County of Los Angeles within the State of California. During all relevant time, Plaintiff ISELA HERNANDEZ is Plaintiff's RUBEN JUAREZ's lawful wife.
- 2. During all relevant time, the alleged injuries occurred in the County of Los Angeles within the State of California.
- 3. Defendant PRECISION VALVE & AUTOMATION, INC. ("PVA") is a New York Corporation and its principal place of business is 1 Mustang Drive, Cohoes, New York, 12047.
- 4. Defendant PVA designed, manufactured, and sold PVA 350, a benchtop dispensing / coating system that sprays chemicals to circuit boards.
- 5. Before 2012, PVA designed, manufactured, and sold at least a PVA 350 to one of Space Exploration Technologies Corp. ("Space X") California locations in Hawthorne, CA, a County of Los Angeles.
- 6. On information and belief, before the sales of the PVA 350, PVA had samples of the chemicals to be sprayed by the PVA 350. As a result, PVA knew or should have known the toxicity of the chemicals to be used by the PVA 350.
- 7. Plaintiffs are unaware of the true names and capacities of those
 Defendants sued herein as DOES 1-20, inclusive, and therefore sues said
 Defendants by such fictitious names. Plaintiffs will amend this Complaint to allege
 the true names and capacities of said Defendants, when the same have been
 ascertained, together with such other charging allegations as may be appropriate.
- 8. Plaintiffs are informed and believe, and thereupon allege, that each Defendant designated as a DOE is responsible, negligently or in some other actionable manner, for the events and happenings hereafter referred to, and caused injuries and damages proximately thereby to plaintiffs, as hereinafter alleged, either

- 9. Plaintiffs are informed and believe, and thereupon allege, that at all times mentioned herein, defendants and each of them, were the agents, servants, employees, independent contractors and/or joint venturers of their co-defendants and were, as such, acting within the scope, course and authority of said agency, employment, contract, and/or joint venture, or acting in the concert, and that each and every defendant, as aforesaid, when acting as a principal, was negligent in the selection, hiring, training, control, and supervision of each and every other defendant as an agent, servant, employee, independent contractor and/or joint venture.
- 10. At some or all relevant herein, each Defendant was the agent of each other defendant, each Defendant was acting within the court and scope of that agency, each Defendant ratified the conduct of the other Defendants with actual and/or constructive knowledge of such conduct, and each Defendant was subject to and under the supervision of the other defendant.

GENERAL ALLEGATIONS

- 11. PVA 350 is a benchtop dispensing / coating system that sprays chemicals to circuit boards, manufactured, designed, supplied, installed, inspected, repaired, and sold by Defendant PVA. Once programmed, PVA can automatically spray chemicals without an attendant constantly on duty.
- 12. PVA 350 does not have an automatic shutoff and does not sound an alarm when the ventilation / exhaust is not in operation. In other words, PVA 350 is designed to continue to spray chemicals even when the ventilation / exhaust is not in operation. Furthermore, there is no warning anywhere about this.
- 13. On information and belief, to add the automatic shutoff, PVA only needs to include an airflow sensor or something similar.

- 14. On January 2012, Plaintiff RUBEN JUAREZ started working for Space X as a programmer for a PVA 350 that sprayed chemicals to circuit boards at Space X's Hawthorne, CA location. Plaintiff RUBEN JUAREZ worked there with the PVA 350 until May or June of 2014.
- 15. During Plaintiff RUBEN JUAREZ's time at Space X, Plaintiff RUBEN JUAREZ was in charge of programming the PVA 350 to spray Arathane® 5750A, Arathane® 5750B, Arathane® 5750A/B, and Humiseal®, Humiseal® thinner.
- 16. PVA trained Plaintiff RUBNE JUAREZ that in order to verify whether the equipment correctly sprayed the chemicals, Plaintiff RUBNE JUAREZ had to stick his head into the spraying chamber of the conformal coating machine to verify. He had to do this because the spray is usually transparent and is very fine with tiny thickness and therefore, a naked eye cannot identify whether or not certain part of the circuit board has been sprayed or the thickness of the spray. The only way to verify this is to use a black light and poke his head inside the PVA 350 to check. He could not take the circuit board out of the PVA 350 to verify this because it is wet and thus, any handling of the board would destroy the accuracy of the spray.
- 17. During Plaintiff RUBEN JUAREZ's time at Space X from 2012 to 2014, he had confirmation that the ventilation system to the PVA 350 was not in operation many times: he asked his co-worker why it always smelt so bad in the room, the co-worker told Mr. Juarez that he just realized that he had forgotten to turn on the ventilation system.
- 18. When the exhaust fan was not in operation, Plaintiff RUBEN JUAREZ unknowingly breathed in the chemicals during the verification process because his head was directly emerged inside the PVA 350 with the toxic chemicals floating inside it.

9

10

11 12 13

14 15

16

17 18

19

21

20

23

22

24

25 26

27

- 19. In addition, when the exhaust fan was not in operation, the chemicals leaked out of the PVA 350. Plaintiff RUBEN JUAREZ on average spent about 60% of his days standing right next to the PVA 350.
- 20. The MSDS of Arathane® 5750A shows that it contains chemicals toluene, diphenylmethane 4, 4'-diisocyanate, MDI Homopolymer, methylenediphenyldiisocryanate ("MDI"), and triethyl phosphate. It further provides that the chronic health effects from the exposure to the chemicals "can cause target organ damage" that include "upper respiratory tract," "the nervous system . . . brain, central nervous system (CNS)."
- The MSDS of Arathane® 5750B shows that it contains chemicals 21. toluene, hydroxylated polybutadiene, methyl ethyl ketone, 1, 1'phenyliminodipropan-2-ol. It further provides that the chronic health effects of exposure to the chemicals "can cause target organ damage" including "the nervous system . . . brain, gastrointestinal tract, central nervous system (CNS)." Overexposure will aggravate the medical conditions.
- The MSDS of Humiseal® shows that it contains chemicals toluene, 22. acetone, xylene, ethyl benzene, methyl ethyl ketone, dimethyl ether, heptane, ethyl 3 ethoxy propionate, and oil mod. Polyurethane. It further provides that inhalation of the chemicals can "[c]ause irritation of nasal passages and throat" and "stupor (central nervous system depression)." "Significant exposure to these chemicals may adversely affect people with chronic disease of the respiratory system" and "central nervous system." And an inhalation may "cause mild nausea/dizziness."
- The MSDS of Humiseal® thinner 521 EU that it contains chemicals 23. xylene. It further provides "[s]ignificant exposure to these chemicals may adversely affect people with chronic disease of the respiratory system [and] central nervous system." Inhalation may cause nausea/dizziness.
 - The scientific community has generally accepted the effects of 24.

1	prolonged exposure to these chemicals. For example, Center of Disease Control's					
2	("CDC") publishes that "[s]ymptoms of toluene poisoning include CNC effects					
3	(headache, dizziness, ataxia, drowsiness, euphoria respiratory depression,					
4	nausea electrolyte imbalances)." United States Department of Labor					
5	Occupational Safety and Health Administration notes that symptoms of toluene					
6	exposure include "weakness, exhaustion, confusion, euphoria, dizziness, headache					
7	anxiety, muscle fatigue, insomnia" and that "long term and repeated workplace					
8	exposure to toluene affect the central nervous system." Environmental Protection					
9	Agency ("EPA") also notes that chronic effect of toluene exposure can cause "CNS					
10	depression," leading to drowsiness, headache, dizziness, and neurobehavioral					
11	effects.					
12	25. Similarly, symptoms from exposure to MDI include "headache, sore					
13	throat chest tightness." A study of 203 school children who were exposed to					
14	MDI shows that 70.9% reported headache, and 62.6% reported nausea. The effects					
15	of chronic exposure of MDI include "headache, nausea and muscle aches. "There					
16	are also case reports of neurological effects" of "headaches, forgetfulness, mood					
17	alterations, irritability, and difficulty concentrating." "[T]here was evidence of					
18	emotional distress in the form of depression, anxiety, and altered mentation."					
19	On information and belief, before a benchtop dispensing system is					
20	designed and manufactured by PVA, Space X sends samples of its toxic chemicals					
21	to PVA for customization. So, PVA knew or should have known the exact type of					
22	chemicals used by its PVA 350 and the dangerous health consequences from					

es of its toxic chemicals nown the exact type of chemicals used by its PVA 350 and the dangerous health consequences from exposure to these chemicals if the exhaust/ventilation is not in operation.

27. Plaintiff RUBEN JUAREZ, a previously healthy man, who rarely went to see doctors, after six months into the job, on June 27, 2012, went to urgent care for palpitations and presyncope (lightheadedness, muscular weakness, blurred vision, and feeling faint). He also complained about shortness of breath. All of

23

24

25

26

5

10

13

18 19

20

21 22

24

25

23

26 27

- these symptoms are well documented as chronic exposure to these toxic chemicals by the scientific community.
- From June of 2012 to present, Plaintiff RUBEN JUAREZ has had over 9 hospitalizations for symptoms associated with toluene, MDI, and other toxic chemical exposure. In addition, he has had at least 21 visits to urgent care /emergency room for symptoms associated with the toxic chemical exposure.
- His current medications include Oxycodne, Norco, Topamax, 29. Depakote, and Ondansetron for migraine, Wellbutrin and Xanax for depression, Flonase and Allegra-D for respiratory issues, Deltasone for chest tightness, and Protonix for stomach problems causing from the drug cocktail.
- 30. His current conditions include severe headache, nausea, short of breath, dizziness, memory loss, out of balance, respiratory issues, and stomach pain from the medications. He also has suicidal thoughts once a week: sometimes his migraines are so severe that he hopes that he just does not wake up the next day. He also has sleeping problems.
- 31. Due to the continuing medical treatment, hospitalization, and urgent care visits, Plaintiff has not worked since May or June of 2014.
- Plaintiff RUBEN JUAREZ lives with his 12-year-old daughter and his 32. wife Plaintiff ISELA HERNANDEZ.
- 33. During the entire time, none of the treating physicians suspected that chemical exposures could have been the cause of his symptoms, due to the fact that none knew that Plaintiff RUBEN JUAREZ was working with chemicals. His medical records list his employment as "computer programmer."
- Up until May of 2015, Plaintiff RUBEN JUAREZ thought that his injury was caused by lead solder wire and cleaning solution to clean electronic parts operated by other Space X employees near Plaintiff's work station. The solder wire and the cleaning solution had nothing to do with the PVA 350—they were not even

Case	2:17-cv-03342-ODW-GJS Document 66-38 Filed 09/10/18 Page 9 of 12 Page ID #:4146						
1	housed in the same location as the PVA 350. It was not until May of 2015, when						
2	Plaintiff Juarez saw the MSDS sheets from Space X that he first saw that the solder						
3	wire was actually lead-free and the detergent was only alcohol and that he first						
4	suspected that the PVA 350 might have caused his injuries. Therefore, despite						
5	diligent investigation of the circumstances of the injury, Plaintiff RUBEN JUAREZ						
6	could not have reasonably discovered facts supporting the cause of action against						
7	PVA within the application statute of limitations period.						
8	FIRST CAUSE OF ACTION						
9	NEGLIGENCE						
10	(Against all Defendants)						
11	35. Plaintiffs refer to paragraph 1-34 above and incorporate them into this						
12	cause of action as though fully set forth herein.						
13	Defendants designed, manufactured, supplied, installed, inspected, and						
14	repaired the PVA 350.						
15	First, Defendants were negligent in designing, manufacturing,						
16	supplying, installing, inspecting, and repairing the PVA 350. In particular,						
17	Defendants failed to use the amount of care in designing, manufacturing,						
18	inspecting, installing, and repairing the PVA 350 that a reasonably careful designer,						
19	manufacturer, supplier, installer, repairer would use in similar circumstances to						
20	avoid exposing Plaintiff RUBEN JUAREZ, a programmer of the PVA 350, to a						
21	foreseeable risk of harm. Furthermore, Defendants' design violated Cal-OSHA,						
22	which requires that "When spray is automatically applied without an attendant						
23	constantly on duty, the operating control of spray apparatus shall be so arranged						
24	that spray cannot be applied unless exhaust fans are in operation." (Title 8 of Cal.						
25	Code of Regulations, § 5153.)						
26	Second, Defendants knew or reasonably should have known that the						
27	PVA 350 was dangerous or was likely to be dangerous when used or misused in a						
28	8						
	FIRST AMENDED COMPLAINT 627						

Case 2	2:17-cv-03342-ODW-GJS	Document 66-38 #:4149	Filed 09/10/18	Page 12 of 12	Page ID
1					
1	DATED: April 24, 20	18	/s/Daniel K. Daniel K. B.	<u>Balaban</u> alaban, Esq.,	
2			Attorneys fo	or Plaintiffs	
3			RUBEN JU. HERNAND	AREZ and ISEI EZ	LA .
5			TIERC VII VE	L	
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					
24					
25					
26					
27					
28			44		
		FIRST, AMEND	11 DED COMPLAI	NT	
		FIRSTAMENT	86 COMI LAI	.1 1 1	630